

Fraction - Decimal Conversion Chart

	<u>Inches</u>	<u>Millimeters</u>		<u>Inches</u>	<u>Millimeters</u>	
	$\frac{1}{64}$	.015625		$\frac{33}{64}$	.515625	13.0969
$\frac{1}{32}$		.03125		$\frac{17}{32}$	.53125	13.4938
	$\frac{3}{64}$	.046875		$\frac{35}{64}$	.546875	13.8907
$\frac{1}{16}$		.0625		$\frac{9}{16}$	.5625	14.2876
	$\frac{5}{64}$	.078125		$\frac{37}{64}$	.578125	14.6844
$\frac{3}{32}$		.09375		$\frac{19}{32}$	.59375	15.0813
	$\frac{7}{64}$	.109375		$\frac{39}{64}$	.609375	15.4782
$\frac{1}{8}$		.125		$\frac{5}{8}$	.625	15.8751
	$\frac{9}{64}$	.140625		$\frac{41}{64}$	.640625	16.2719
$\frac{5}{32}$		.15625		$\frac{21}{32}$	.65625	16.6688
	$\frac{11}{64}$	.171875		$\frac{43}{64}$	.671875	17.0657
$\frac{3}{16}$		.1875		$\frac{11}{16}$	.6875	17.4626
	$\frac{13}{64}$	.203125		$\frac{45}{64}$	.703125	17.8594
$\frac{7}{32}$		.21875		$\frac{23}{32}$	.71875	18.2563
	$\frac{15}{64}$	.234375		$\frac{47}{64}$	.734375	18.6532
$\frac{1}{4}$		.250		$\frac{3}{4}$	.750	19.0501
	$\frac{17}{64}$	.265625		$\frac{49}{64}$	.765625	19.4470
$\frac{9}{32}$		.28125		$\frac{25}{32}$	.78125	19.8438
	$\frac{19}{64}$	.296875		$\frac{51}{64}$	.796875	20.2407
$\frac{5}{16}$		.3125		$\frac{13}{16}$	.8125	20.6376
	$\frac{21}{64}$	.328125		$\frac{53}{64}$	.828125	21.0345
$\frac{11}{32}$		.34375		$\frac{27}{32}$	.84375	21.4313
	$\frac{23}{64}$	.359375		$\frac{55}{64}$	.859375	21.8282
$\frac{3}{8}$		.375		$\frac{7}{8}$	.875	22.2251
	$\frac{25}{64}$	.390625		$\frac{57}{64}$	.890625	22.6220
$\frac{13}{32}$		.40625		$\frac{29}{32}$	.90625	23.0188
	$\frac{27}{64}$	.421875		$\frac{59}{64}$	.921875	23.4157
$\frac{7}{16}$		.4375		$\frac{15}{16}$	.9375	23.8126
	$\frac{29}{64}$	.453125		$\frac{61}{64}$	.953125	24.2095
$\frac{15}{32}$		.46875		$\frac{31}{32}$	.96875	24.6063
	$\frac{31}{64}$	.484375		$\frac{63}{64}$	.984375	25.0032
$\frac{1}{2}$		.500		1	1.000	25.4001